



Properly used, the ENICAR  
SHERPA SUPER-DIVETTE ren-  
ders invaluable service. Please  
read the Directions for Use.  
They contain a very clear  
practical example.

**SUPER-DIVETTE**



**ENICAR**

Your Jeweler:

Printed in Switzerland



**ENICAR**



Directions for Use

**ENICAR**

*Sherpa*



C

A

E

D

The ENICAR SHERPA SUPER-DIVETTE is extremely easy to use, as the following example shows:

Example: It's 10:12 a. m. You plan to spend 45 minutes at a depth of 80 feet. For surfacing (including decompression) you count another two minutes.

With your SHERPA SUPER-DIVETTE you can keep a close watch on the passing of these 47 minutes, like this:

- With crown (A) turn ring (B) until the great luminous arrow (C) is opposite the tip of the minute hand.
- During the dive, look at your watch from time to time. As soon as the minute hand is opposite the figure 40 on ring (B), it is time to surface. Ten feet below the

surface stop for decompression, which comes to an end as soon as the minute hand points to 42 on ring (B), indicating that the last 2 minutes have elapsed.

To set the date, using crown (D) turn the hands from midnight back to 8 p. m., then forward again to midnight, thus changing the date. Repeat until the required date appears in the window (E). When finally setting the right time, turn the hands forward. If it is after 12 noon, you must turn the hands on through another 12 hours, so that the date will change at midnight.