



Properly used, the ENICAR
SHERPA OPS renders invaluable
service. Please read the
Directions for Use. They contain
a very clear practical
example.

OPS



ENICAR

Your Jeweler:

Printed in Switzerland



ENICAR



Directions for Use

ENICAR

Sherpa



C

A

E

D

The ENICAR SHERPA OPB is extremely easy to use, as the following example shows:

Suppose it's 10:12 a. m. You plan to spend 40 minutes at a depth of 80 feet. For surfacing (including decompression) you count another two minutes.

With your SHERPA OPB you can keep a close watch on the passing of these 42 minutes, like this:

- Pull out crown (A) and turn ring (B) until the green luminous arrow (C) is opposite the tip of the minute hand. Block up the ring by pushing back the crown (A).
- During the dive, look at your watch from time to time. As soon as the minute hand is opposite the figure 40

on ring (B), it is time to surface. Ten feet below the surface stop for decompression, which comes to an end as soon as the minute hand points to 42 on ring (B), indicating that the last 2 minutes have elapsed.

To set the date, using crown (D) turn the hands from midnight back to 8 p. m., then forward again to midnight, thus changing the date. Repeat until the required date appears in the window (E). When finally setting the right time, turn the hands forward. If it is after 12 noon, you must turn the hands on through another 12 hours, so that the date will change at midnight.